

Spare Parts Catalogue

MD-CO-RO-32

**MODELS TYPE :
(B025DE0, B025EL0)**

This document is intended to list the main changes and updates of the spare parts catalogue introduced into the mentioned model in order to simplify the service and spare parts management.

The reading of the degree of interchangeability of the new components is explained in the following table:

| | |
|-----------|---|
| YY | Old and new components can be installed on new and old robots (interchangeability in both directions) |
| NY | The new components can be installed both on new and old robots whereas old components can not be installed on new robots. |
| NN | The new components can be installed only on new robots and the old ones only on old robots (lack of interchangeability). |

Zucchetti Centro Sistemi Spa.

| Catalog. | TAB. | RIF. | Description | Old-Item | New-Item | Exchang. | Note |
|--|------|------|--------------------------|--------------|--------------|----------|---------------|
| 2022 Robots (B025DE0, B025EL0, B029DE0, B029EL0) | | | | | | | |
| 1.2 | 03 | 37 | Lift board | 015E00100A | L25E00400A | NY | Different p/n |
| 1.2 | 04 | 13 | Complete base | L25Z08800A_R | L25Z08800B_R | YY | Different p/n |
| 1.2 | 03 | 38 | Chassis bumper | L25Z06700A_R | L25Z06600A | YY | Different p/n |
| | | | | | | | |
| 1.1 | | | | | | | Update prices |
| 1.1 | 04 | 14 | Transmitter box assembly | 015Z10400A_R | 015Z10400B_R | YY | Different p/n |
| 1.1 | 04 | 12 | Recharging contact | L20Z04600B | L20Z22549A | YY | Different p/n |
| 1.1 | 04 | 7 | Transmitter box | 015Z17000A_R | L20Z22559A_R | YY | Different p/n |
| 1.1 | 04 | 04 | Transmitter | 015E00700A | 015E00700A_R | YY | Different p/n |
| 1.1 | 04 | 15 | LED board | | 015A00700A | YY | Add new item |

